## **Under Review Notification**

Raised By: Vanessa Morel Product #: RBW1805G01731-3G

Date: 2019.10.23 Product Name: MVA REMOVAL TOOL

		"Y" or "N" Required for Each Part							t		
		Do not leave blank									
Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers		Quarantine Tooling (Jigs, Fixtures, etc.)	Re-Work Stock	IPP Under Review (Enginer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")	Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
RBW1805G01731-3G	RBW1805G01731-3G Rev 3	Υ	Υ	Ν	Υ	Υ	Z	N	Ν	19-938	See below

## Description of Issue:

Issues stated on ADR (Fit issues)

RBW1805G01731-3G and items -1, -3, -5, -7 and -9 must be put on **HOLD** in Plex

RBW1805G01731-3G Finish good stock can be use as is

Items -1, -3, -5, -7 and -9 must be put in quarantine

No new manufacturing is permitted until Engineering release new Rev

Can remain on website with a note to contact sales for a quote. They must NOT be able to put the tool into cart

'P" Part must be put on HOLD in Plex as well

Distribution: VP Operations Director of Engineering Customer Support Manager Technical Support

Director of Operations Chief Engineer Production Engineers Production Engineers Product Manager - Solutions Provider

Director Quality Assurance Engineering Project Managers Production Planners Supply Chain Director / Senior Buyer

QC Coordinator Engineering Clerk Purchasing Manager Marketing Eugene